


19 362 000 VERIS 5-HOLE BATH/SHOWER COMBINATION



SPARE PARTS, August 2008 – now

- 1: Handle (Spare part-nr. 48015000)
- 2: Handle (Spare part-nr. 48016000)
- 3: Ceramic headpart 3/4", 180° (Spare part-nr. 45887000)
- 4: Ceramic headpart 3/4", 180° (Spare part-nr. 45888000)
- 5: Seat 3/4" (Spare part-nr. 45345000)
- 6: Repl.kit f.shank fastening 3/4" (Spare part-nr. 45444000)
- 7: Tube (Spare part-nr. 48018000)
- 8: Spout (Spare part-nr. 13250000)
- 8.1: Set of screws (Spare part-nr. 46670000)
- 8.2: Sealing washer (Spare part-nr. 0128500M)
- 8.3: Mousseur (Spare part-nr. 13922000)
- 9: Tube (Spare part-nr. 48019000)
- 10: Screw joint (Spare part-nr. 45044000)
- 11: Dirt strainer (Spare part-nr. 0700200M)
- 12: Cone nut (Spare part-nr. 08864000)
- 13: Diverter knob (Spare part-nr. 45997000)
- 14: Diverter (Spare part-nr. 45443000)
- 14.1: O-ring $\varnothing 6 \times \varnothing 2$ (Spare part-nr. 0128300M)
- 14.2: Seat washer (Spare part-nr. 0120500M)
- 15: Non-return valve (Spare part-nr. 08565000)
- 16: Tube (Spare part-nr. 07300000)
- 17: Metal hose (Spare part-nr. 28146000)
- 18: Compression spring (Spare part-nr. 00869000)