


21 337 000 COSTA SINGLE-HOLE BASIN MIXER



SPARE PARTS, October 2007 – now

- 1: Headpart 1/2" (Spare part-nr. 45534000)
- 1.1: Costa handle, blue/red (Spare part-nr. 45970000)
- 1.1.1: Repl. kit f.handle fastening (Spare part-nr. 0538600M)
- 1.2: Headpart 1/2" (Spare part-nr. 07146000)
- 1.2.1: O-ring $\varnothing 6 \times \varnothing 2$ (Spare part-nr. 0128300M)
- 1.2.2: O-ring $\varnothing 18.2 \times \varnothing 1.7$ (Spare part-nr. 0392400M)
- 1.2.3: Ball seal dia. 9x6.8 mm (Spare part-nr. 0529100M)
- 2: Swivel tube spout (Spare part-nr. 13072000)
- 2.1: Mousseur (Spare part-nr. 13928000)
- 2.2: O-ring dia. 12x2 mm (Spare part-nr. 0128000M)
- 3: Escutcheon (Spare part-nr. 45217000)
- 4: Shank mounting kit (Spare part-nr. 46249000)
- 5: Chain support (Spare part-nr. 06815000)