


24 033 000 PARKFIELD WIDASET BIDET




SPARE PARTS, November 2016 – now

- 1: Parkfield lever blue/red US (Spare part-nr. 48205000)
- 2: Ceramic headpart, 1/2" (Spare part-nr. 45882000)
- 2.1: O-ring $\varnothing 18.2 \times \varnothing 1.7$ (Spare part-nr. 0392400M)
- 3: Ceramic headpart, 1/2" (Spare part-nr. 45883000)
- 3.1: O-ring $\varnothing 18.2 \times \varnothing 1.7$ (Spare part-nr. 0392400M)
- 4: Shank fastening assembly (Spare part-nr. 45025000)
- 5: Repl. kit f. seal (Spare part-nr. 45027000)
- 6: Ball rod (Spare part-nr. 48332000)
- 7: Plug (Spare part-nr. 48331000)
- 8: Flexible connection hose (Spare part-nr. 45704000)
- 9: Vacuum Breaker (Spare part-nr. 45852000)
- 9.1: Shank mounting kit (Spare part-nr. 45855000)
- 9.2: Non-return valve (Spare part-nr. 08565000)
- 9.3: Fibre seal dia. 12x2 mm (Spare part-nr. 0138900M)
- 10: Flexible connector M10x1xM15x1x350 (Spare part-nr. 46254000)
- 11: Coupling nut 1/2" x 10.5 mm (Spare part-nr. 1290100M)*
- 12: Coupling nut 1/2" x 14.5 mm (Spare part-nr. 1290200M)*

* Optional accessories


24 033 000 PARKFIELD WIDASET BIDET



SPARE PARTS, August 2016 – November 2016

- 1: Parkfield lever blue/red US (Spare part-nr. 48205000)
 - 2: Ceramic headpart, 1/2" (Spare part-nr. 45882000)
 - 2.1: O-ring $\varnothing 18.2 \times \varnothing 1.7$ (Spare part-nr. 0392400M)
 - 3: Ceramic headpart, 1/2" (Spare part-nr. 45883000)
 - 3.1: O-ring $\varnothing 18.2 \times \varnothing 1.7$ (Spare part-nr. 0392400M)
 - 4: Shank fastening assembly (Spare part-nr. 45025000)
 - 5: Repl. kit f. seal (Spare part-nr. 45027000)
 - 6: Pop-up waste set (Spare part-nr. 28957000)
 - 6.1: Plug (Spare part-nr. 45324000)
 - 6.2: Housing (Spare part-nr. 01153000)
 - 6.3: Ball rod (Spare part-nr. 45264000)
 - 7: Jointed rod (Spare part-nr. 06085000)
 - 8: Flexible connection hose (Spare part-nr. 45704000)
 - 9: Vacuum Breaker (Spare part-nr. 45852000)
 - 9.1: Shank mounting kit (Spare part-nr. 45855000)
 - 9.2: Non-return valve (Spare part-nr. 08565000)
 - 9.3: Fibre seal dia. 12x2 mm (Spare part-nr. 0138900M)
 - 10: Flexible connector M10x1xM15x1x350 (Spare part-nr. 46254000)
 - 11: Coupling nut 1/2" x 10.5 mm (Spare part-nr. 1290100M)*
 - 12: Coupling nut 1/2" x 14.5 mm (Spare part-nr. 1290200M)*
- * Optional accessories

24 033 000 PARKFIELD WIDASET BIDET




SPARE PARTS, December 2013 – August 2016

- 1: Parkfield lever blue/red US (Spare part-nr. 48205000)
- 2: Ceramic headpart, 1/2" (Spare part-nr. 45882000)
- 2.1: O-ring $\varnothing 18.2 \times \varnothing 1.7$ (Spare part-nr. 0392400M)
- 3: Ceramic headpart, 1/2" (Spare part-nr. 45883000)
- 3.1: O-ring $\varnothing 18.2 \times \varnothing 1.7$ (Spare part-nr. 0392400M)
- 4: Shank fastening assembly (Spare part-nr. 45025000)
- 5: Coupling nut 1/2" x 14.5 mm (Spare part-nr. 1290200M)
- 5.1: Fibre seal dia. 12x2 mm (Spare part-nr. 0138900M)
- 6: Repl. kit f. seal (Spare part-nr. 45027000)
- 7: Pop-up waste set (Spare part-nr. 28957000)
- 7.1: Plug (Spare part-nr. 45324000)
- 7.2: Housing (Spare part-nr. 01153000)
- 7.3: Ball rod (Spare part-nr. 45264000)
- 8: Jointed rod (Spare part-nr. 06085000)
- 9: Spray faceplate (Spare part-nr. 02664000)
- 10: Flexible connection hose (Spare part-nr. 45704000)
- 11: Vacuum Breaker (Spare part-nr. 45852000)
- 11.1: Double ball vacuum breaker (Spare part-nr. 45854000)
- 11.2: Shank mounting kit (Spare part-nr. 45855000)
- 11.3: Non-return valve (Spare part-nr. 08565000)
- 11.4: Fibre seal dia. 12x2 mm (Spare part-nr. 0138900M)
- 12: Flexible connector M10x1xM15x1x350 (Spare part-nr. 46254000)
- 13: Coupling nut 1/2" x 10.5 mm (Spare part-nr. 1290100M)*

* Optional accessories

24 033 000 PARKFIELD WIDSET BIDET



SPARE PARTS, February 2012 – December 2013

- 1: Parkfield lever blue/red US (Spare part-nr. 48205000)
- 2: Ceramic headpart, 1/2" (Spare part-nr. 45882000)
- 2.1: O-ring $\varnothing 18.2 \times \varnothing 1.7$ (Spare part-nr. 0392400M)
- 3: Ceramic headpart, 1/2" (Spare part-nr. 45883000)
- 3.1: O-ring $\varnothing 18.2 \times \varnothing 1.7$ (Spare part-nr. 0392400M)
- 4: Shank fastening assembly (Spare part-nr. 45025000)
- 5: Coupling nut 1/2" x 14.5 mm (Spare part-nr. 1290200M)
- 5.1: Fibre seal dia. 12x2 mm (Spare part-nr. 0138900M)
- 6: Screw connection for bidet body (Spare part-nr. 45026000)
- 7: Repl. kit f. seal (Spare part-nr. 45027000)
- 8: Pop-up waste set (Spare part-nr. 28957000)
- 8.1: Plug (Spare part-nr. 45324000)
- 8.2: Housing (Spare part-nr. 01153000)
- 8.3: Ball rod (Spare part-nr. 45264000)
- 9: Jointed rod (Spare part-nr. 06085000)
- 10: Rim spray (Spare part-nr. 24210000)
- 10.1: Spray faceplate (Spare part-nr. 02664000)
- 11: Flexible connection hose (Spare part-nr. 45704000)
- 12: Vacuum Breaker (Spare part-nr. 45852000)
- 12.1: Double ball vacuum breaker (Spare part-nr. 45854000)
- 12.2: Shank mounting kit (Spare part-nr. 45855000)
- 12.3: Non-return valve (Spare part-nr. 08565000)
- 12.4: Fibre seal dia. 12x2 mm (Spare part-nr. 0138900M)
- 13: Flexible connector M10x1xM15x1x350 (Spare part-nr. 46254000)