

26 336 000 ATLANTA SHOWER MIXER

No exploded view is available for this spare part list.

SPARE PARTS, January 1988 – now

- 1: Treflor handle blue/red (Order-nr. 45124000)
- 1.1: Handle fixation (Order-nr. 45123000)
 - 1.1.1: Repl. kit f.handle fastening (Order-nr. 0538600M)
- 2: Ceramic headpart, 1/2" (Order-nr. 45346000)
- 2.1: O-ring $\varnothing 18.2 \times \varnothing 1.7$ (Order-nr. 0392400M)
- 3: Screw joint (Order-nr. 45040000)